

WinDarab V7-Shortcuts



BOSCH

Navigation	Channels	Display
<↑↓> Move crosshairs	Space Set tag	G Toggle Grid
Ctrl+← Scroll log data	2 Space Delete tag	File Options
Ctrl+→ Scroll log data	B Blink channel	F4 Activate „shift file“
+ Zoom in	Ctrl+0 Show Zero line	F5 Show settings (measurement element)
- Zoom out	Ctrl+9 Show Constant line	F6 Load new config
Ctrl+Z Undo zoom	C Color	F7 Save config
A Zoom all	H Hide/unhide	F9 Load desktop
F Zoom fast lap	I Channel info	F12 Toggle desktop
L Zoom lap	Y Reset Y range	Insert Local add menu
M Zoom marked rg.	Ctrl+A Select all channels in area	Delete Local delete menu
N Next lap	Ctrl+Shift+A Select all channels in oscilloscope	R Replace
P Previous lap	Ctrl+Y Auto Y range	Views
S Segment	Z Set channel zero	F1 Help
Menu Options	D Display options	F2 Add Worksheet
Ctrl+E Open file		F3 Filter channel list
Ctrl+R Read data		
Ctrl+S Close data		

51 mm

75 mm

WinDarab V7-Shortcuts



BOSCH

Navigation	Channels	Display
<↑↓> Move crosshairs	Space Set tag	G Toggle Grid
Ctrl+← Scroll log data	2 Space Delete tag	File Options
Ctrl+→ Scroll log data	B Blink channel	F4 Activate „shift file“
+ Zoom in	Ctrl+0 Show Zero line	F5 Show settings (measurement element)
- Zoom out	Ctrl+9 Show Constant line	F6 Load new config
Ctrl+Z Undo zoom	C Color	F7 Save config
A Zoom all	H Hide/unhide	F9 Load desktop
F Zoom fast lap	I Channel info	F12 Toggle desktop
L Zoom lap	Y Reset Y range	Insert Local add menu
M Zoom marked rg.	Ctrl+A Select all channels in area	Delete Local delete menu
N Next lap	Ctrl+Shift+A Select all channels in oscilloscope	R Replace
P Previous lap	Ctrl+Y Auto Y range	Views
S Segment	Z Set channel zero	F1 Help
Menu Options	D Display options	F2 Add Worksheet
Ctrl+E Open file		F3 Filter channel list
Ctrl+R Read data		
Ctrl+S Close data		

51 mm

75 mm

WinDarab V7-Shortcuts



BOSCH

Navigation	Channels	Display
<↑↓> Move crosshairs	Space Set tag	G Toggle Grid
Ctrl+← Scroll log data	2 Space Delete tag	File Options
Ctrl+→ Scroll log data	B Blink channel	F4 Activate „shift file“
+ Zoom in	Ctrl+0 Show Zero line	F5 Show settings (measurement element)
- Zoom out	Ctrl+9 Show Constant line	F6 Load new config
Ctrl+Z Undo zoom	C Color	F7 Save config
A Zoom all	H Hide/unhide	F9 Load desktop
F Zoom fast lap	I Channel info	F12 Toggle desktop
L Zoom lap	Y Reset Y range	Insert Local add menu
M Zoom marked rg.	Ctrl+A Select all channels in area	Delete Local delete menu
N Next lap	Ctrl+Shift+A Select all channels in oscilloscope	R Replace
P Previous lap	Ctrl+Y Auto Y range	Views
S Segment	Z Set channel zero	F1 Help
Menu Options	D Display options	F2 Add Worksheet
Ctrl+E Open file		F3 Filter channel list
Ctrl+R Read data		
Ctrl+S Close data		

51 mm

75 mm